




A	M6*16mm x4	C	φ6*φ18 x4	E	x1	G	x1				
B	M10*30mm x3	D	x1	F	x1	H	x1				



General Care :

\*For cleaning wipe the surface with a damp (not wet) cloth or sponge or wipe dry with a clean lint free cotton cloth.

Pokyny k ošetrovaniu:

\*K čisteniu používajte vlhký handričku alebo houbu, alebo ho otřete suchým nechlupatým bavlněným handříkem.

Pokyny k ošetrovaniu:

\*Na čistenie používajte vlhkú handričku alebo špongiu, alebo ho utrite suchou nechlpatou bavlnenou handričkou.

