
















A1	$\phi 8 \times 36$	x24
B5	$\times 16$	
B4	x16	
E1	Kr0	x4
D10	$3,5 \times 13$	x10
E2	H0	x4
EK2	6,3x13	x8
H6	L-246mm	x2
D8	5x13	x4
P1	x6	
D18	M4x9mm	x2
UP9	3x16	x6
D11	3.5x25	x4
L1	x1	
G1	Lem	x1
KR2	x1	
UL	L-224	x3
I11	x4	
D22	4x40	x1
UP6	4x30	x6
G2	S-4	x1




1




2








3




4




5**6****7****a=b**

90°


8



9



10



11

