




















60 min.




A1		$\phi 8 \times 36$	x12
C6		L-260	x1
B5			x4
UP9		3x16	x4
B4			x4
G8		L-1946	x1
G5		#15	x4
UL		L-224	x1
B11		7x50	x8
UP6		4x30	x2
I1		$\phi 2$	x8
D11		3.5x25	x4
G7			x4
I11			x4
S1			x14
E1		Kr0	x6
L1			x1
D10		3.5x13	x14
KR2			x1
E2		H0	x6
D22		4x40	x1
EK2		6,3x13	x12
G2		S-4	x1



1




D11	x	3.5x25	x4	A1	x	$\phi 8 \times 36$	x12
I11	x	4		B5	x	4	
E2	H0	x6		B4	x	4	
EK2	$6,3 \times 13$	x12		G7	x	4	




C6	L-260	x1
UP9	3x16	x4


2




3





4

**S1** x14

5

**UL**
L-224 x1**E1**
Kr0 x6**UP6**
4x30 x2**D10**
3,5x13 x12

6**7**